



Key

- Existing site trees to be removed
- Existing trees to be retained and protected
- Existing block footpath to be removed
- Existing bench to be relocated to a different location within the garden

Schedule of trees to be removed.

T02- Horse chestnut	Category B- Tree of moderate quality
T03- Sycamore (Acer pseudoplatanus)	Category B- Tree of moderate quality
T04- Common ash (Fraxinus excelsior)	Category B- Tree of moderate quality
T05- Common ash (Fraxinus excelsior)	Category B- Tree of moderate quality
T07- Common Yew (Taxus baccata)	Category C- Tree of low quality
T08- Common Yew (Taxus baccata)	Category C- Tree of low quality
T09- Sycamore (Acer pseudoplatanus)	Category B- Tree of moderate quality
T11- Norway maple (Acer platanoides)	Category C- Tree of low quality
T12- Sycamore (Acer pseudoplatanus)	Category B- Tree of moderate quality
T13- Small leaf lime (Tilia cordata)	Category C- Tree of low quality
T15- Common Yew (Taxus baccata)	Category C- Tree of low quality
T17- Cherry (Prunus Spp)	Category C- Tree of low quality
T21- Huntingdon Elm	Category C- Tree of low quality
T23- Sycamore (Acer pseudoplatanus)	Category B- Tree of moderate quality
T24- Common Lime (Tilia cordata)	Category B- Tree of moderate quality
T25- Common Lime (Tilia cordata)	Category B- Tree of moderate quality
T26- Common Lime (Tilia cordata)	Category B- Tree of moderate quality
T27- Common Lime (Tilia cordata)	Category B- Tree of moderate quality
T28- Common Lime (Tilia cordata)	Category B- Tree of moderate quality
T29- Common Lime (Tilia cordata)	Category B- Tree of moderate quality
T30- Common Ash (Fraxinus excelsior)	Category D- Standing dead tree

Schedule of trees to be retained

T01- Norway maple (Acer platanoides)	Category B- Tree of moderate quality
T06- Common ash (Fraxinus excelsior)	Category B- Tree of moderate quality
T10- Sycamore (Acer pseudoplatanus)	Category B- Tree of moderate quality
T14- Sycamore (Acer pseudoplatanus)	Category B- Tree of moderate quality
T16- Cherry (Prunus Spp)	Category B- Tree of moderate quality
T18- Sycamore (Acer pseudoplatanus)	Category B- Tree of moderate quality
T19- Plum (Prunus Domestica)	Category C- Tree of low quality
T20- Plum (Prunus Domestica)	Category C- Tree of low quality
T22- Copper Beech (Fagus sylvatica Purpurea)	Category A- Tree of high quality
T31- Common Yew (Taxus baccata)	Category B- Tree of moderate quality

NOTES

Please refer to the Tree Survey carried out by Arbrech for existing trees to be retained and existing trees to be removed. Refer to the Structural Inspection report carried out by RCA Structural Engineering and Design for the inspection of the wall adjacent to Bell Street.

LEGEND

MEASUREMENTS IN METRES UNLESS OTHERWISE STATED

REVISION NOTES	REV	DATE
A Change in height level as requested by the client	06/02/24	
B Change in tree T31 to be retained as requested by client	06/02/24	
C Additions, deletions, etc. indicated on site of trees to be retained and removed (also see revision history table)	20/02/23	
D		

Groundwork East
Mill Green, Hatfield
Herts SG9 6JG
TEL: 01763 269129
EAST: hertfordshire@groundwork.co.uk

CLIENT: Jubilee Garden: Sawbridgeworth
PROJECT ADDRESS: Sawbridgeworth Town Council
PROJECT NUMBER: CM21 9AQ

DATE: August '23
DRAWN BY: GJD
CHECKED: MM
SCALE: 1:200 @ A3
REVISION: B